Kowloon Park - Summary of Co-creation Team Observations 11th May 2019

Positive	Improvements
Clean environment	Unconformable seating Poor anti-mosquito measures and mosquitoes traps are needed Unrepaired facilities such as broken and rusty handrail Uneven road surface
Good accessibility to public transport	 Unclear signage and guidelines More descriptive information should be given Insufficient lighting along the trail A more welcoming entrance is recommended because there are not many people know this trail Accesses are not prominent and unable to provide clear direction
Feedback / Comments	
 Chatting Exercising (i.e. Kung Fu exercise, running) Sitting Resting 	
Unclear instruction Original purpose of facilities cannot be achieved Kids play the fitness equipment inappropriately	
• Facilities' height is not suitable for someone	
Suggested to be replaced with equipment in attractive colour and special texture	
 No CCTV along the trail More lighting should be added to enhance a higher visibility and increase sense of security The trail is concealed by lush plants and this increases the risk of crime 	
Response from participants:	
Uneven road surface Insufficient lighting	
Response from participants:	
• Lack of storage space (people hang their belongings with a pin on the shelter)	
	Clean environment Good accessibility to public transport Feedback / Comments Chatting Exercising (i.e. Kung Fu exercise, running) Sitting Unclear instruction Original purpose of facilities cannot be ac Kids play the fitness equipment inapprop Facilities' height is not suitable for somec Suggested to be replaced with equipmen No CCTV along the trail More lighting should be added to enhance The trail is concealed by lush plants and t <i>Response from participants:</i> Uneven road surface Insufficient lighting <i>Response from participants:</i>

Highlight in workshop- (iii) Greening	Response from participants: • Inadequate flowers • Lack of smell to attract people	
Highlight in workshop- (iv) Use of technology	Response from participants: • Integrate equipment with mobile apps • Making use of QR code or Al	
Considerations of Intergeneration	Engagement: • No gym facilities for children or the disable • Existing exercise equipment tend to attract adult/ female young-old Safety: • The track is too steep - hard for runners/ elderly/ disable to walk • Non-slipped floor surface is suggested to be applied on the inclined path • Uneven ground in some exercise facilities • Elderly may not know how to use the fitness facilities properly (unclear instructions) Interaction • No interaction between users • Not enough space for children to play with parents • Poor seating arrangement that does not facilitate interaction • The necessary of separating different zones should be considered	